08/09/2001, EAST Version: 1.02.0008

Type		#	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Erro
BRS L1	17		359	((flexible or bendable) near tape) same rigid\$		2001/08/09 12:38			0
BRS 1.2	1.2		VO.	assembly and tape and carrier and semicondutor	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2001/08/09 12:41			0
BRS L3	L3		Ŋ	apparatus and tape and carrier and semicondutor	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2001/08/09 12:42			0
BRS L4	1.4		м	(index adj hole) near tape	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2001/08/09 12:44			0
BRS L5	LS		8	(index adj hole) with tape	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2001/08/09 12:47			0
BRS L6	16		20	((index adj hole) same (tape or film)) and (carrier or support)	⊃ <u>,</u> ⊢	2001/08/09 12:52			0
BRS L7	L7		0	(solder adj resist) adj carrier	⊃ . ⊢	2001/08/09 12:54			G.
BRS L8	L <sub>9</sub>		<u>.</u>	(solder adj resist) adj (frame or bar)	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM ; IBM	2001/08/09 12:53			0

08/09/2001, EAST Version: 1.02.0008

$\vdash$	Type	# 12	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Erro
l	BRS	L9	106	(solder adj resist) with carrier	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2001/08/09 12:55			0
10	BRS	L10	4	(solder adj resist) near carrier	L	2001/08/09 12:58			0
H	BRS	L11	11	(index adj hole) with (tape or (thin adj film))	⊃ <u>.</u> ⊬	2001/08/09 13:00			0
12	BRS	L12	447	bt adj resin	⊃ <u>.</u> ⊢	2001/08/09			0
13	BRS	L13	0	L12 near carrier	7 · . 🗀	2001/08/09 13:03			0
14	BRS	L14	14	(bt adj resin) with (carrier or frame or bar or support or reinforcement)	7	2001/08/09 13:15			0
15	BRS	L15	6	L14 and tape	7 · · ·	2001/08/09 13:04			0
16	BRS	117	260	L12 and semiconductor	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/08/09 13:16			O

=	Type	н #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Erro
BRS		L16	1.37	L12 and tape	l –	2001/08/09 13:55			0
BRS	<b>(</b> 0	L18	199	438/111.ccls.	~ · · ·	2001/08/09 13:55			0
BRS	W	L19	5 8	438/111.ccls. and tape	¬	2001/08/09 13:57			0
BRS	S	120	17	438/459.ccls. and tape	⊃ ∿ ⊟	2001/08/09 13:58			0
BRS	S	L21	81	438/113.ccls. and tape	⊃. ⊢	2001/08/09 13:59			0
BRS	Ŋ	L22	95	438/108.ccls. and tape	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/08/09 14:00			0
BRS	W	L23	159	361/778.ccls.	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM	2001/08/09 14:01			0
BRS	S	L24	35	361/779.ccls. and (tape or carrier)	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/03/09 14:06			O

	Type	#	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Erro
25	BRS	125	171	361/807.ccls. and (tape or carrier)	USPAT; US-PGPU B; EPO; 2PO; DERWENT 11:06	2001/08/09 14:06			0